



58650

OEM: N/A

Dry Joint Alternative - Exhaust Manifold Set



**Iron
Casting**



For Mercruiser
GM V6

Elbow + Manifold Replaces
Dry Joint Exhaust System