

**58663**

OEM: N/A

Dry Joint Alternative - Exhaust Manifold Set**Iron
Casting****with 3"
Spacer**

For Mercruiser
GM V8 S.B. with 3" spacer

**Elbow + Manifold Replaces
Dry Joint Exhaust System**

Kit Contains:	QTY	Description	GLM	OEM
	1	Exhaust Elbow	51148	N/A
	1	Exhaust Manifold Ass.	51230	860246A10
	1	Gasket, Elbow	30240	27-863724
	1	Gasket, Manifold	31100	27-33395
	4	Stud	22466	N/A
	4	Nut	21248	11-49838
	1	Hose Fitting with Drain Plug Kit	13990	22-806926A1
	1	Spacer 3"	50300	N/A
	1	Gasket, Elbow	32080	27-863726