

The Aftermarket Marine Parts Newsletter

NEW PRODUCTS



YAMAHA CATALOG GLM No. GYA10V1



Quality Replacement Parts for Yamaha, Suzuki, Honda, Tohatsu & Nissan Visit www.glmmarine.com for E-Catalog



GIMBAL BEARING



GLM No. 21905 OEM: 30-862540A3

GLM Built in the U.S.A.

Alpha One Gen II & Bravo (1998 & Up)





ALUMINUM ANODE



OEM: 688-45271-02

For 60, 70, 90 HP (1984-Up) C60, C75, C85, C90 HP (1994-01) E60, E75, E50, P60, P75, T50 HP



ALUMINUM PENCIL ANODE



GLM No. 11981

OEM: N/A

3/4" x 3-3/8" for 3/4" Plug



WATER PUMP KIT



GLM No. 12277

OEM: 6L2-W0078-00-00

Fits Models: 20 HP (1996-97), 25 HP (1988-98, 2000, 2003-04)



GEARCASE SEAL KIT



OEM: 6H3-W001-22-00, 6H2-W001-20-00

C-60 HP (1996-01), C-70 HP (2000-01), E-60 HP (1995-00), P-60 HP (1991-99) & 60 HP (2001-05), 70 HP (1984-05)



PRI IMOTIOI IS

JOHNSON / EV NRUDE OUTBOARDS



PRESS RELEASE

OMC V6 Conversion Kit GLM No. 58995

GLM's V6 Manifold Conversion Kit is designed to convert OMC Single-Piece Exhaust Manifolds to the more efficient Center Rise Manifolds on all OMC Cobra V6 Engines with GM 262 CID Blocks. For 1989 only! Comes complete with all hardware!



sold separately

2011 TRADESHOWS

October 17-19th - IBEX - Louisville, Kentucky USA

November - Barcelona Boat Show - Barcelona, Spain

November - METS - Amsterdam, Netherlands

TECH TIPS

Care & Maintenance of your GLM Aluminum Manifolds

DO NOT SCRAPE PAINT OFF GASKET SURFACES OF ALUMINUM MANIFOLDS.



The exposure of bare metal will cause corrosion and premature product failure.

Periodic examination of the pencil anodes should be performed throughout the boating season. Pencil anodes are sacrificial and protect the manifold from corrosion. Failure to maintain the pencil anodes will result in premature product failure and voiding of the warranty.



GLM CATALOG SERIES















